## **BUILDING SAFETY CERTIFICATE**

No.

Dated: 03/07/24

Certified that the existing building Saint Soldier Sr. Sec. School (name of the building or premises) at Village Lehranwali Dhani, Tehsil Rania, Distt. Sirsa, State Haryana (address) is having block (s)/Floor (s) as per details below:

Details of Block in school	Block (01)	Block (02)	Block (03)	Block	Block	Block
No. of Floors in the Block	fils+ floor		(00)	(04)	(05)	(06)

The Building is owned/Occupied by Sardar Bachan Singh Memorial Education Trust, Village Lehranwali Dhani, Tehsil Rania, Distt. Sirsa, State Haryana (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Front Cub Division Por Ber Cleros of Name of Department/ Govt.) on...... 02.07.2014 ......(date of inspection) in the presence of Mr. Bikram Jit Singh Manager Sardar Bachan Singh Memorial Education Trust representative) and that the building/premises is fit for occupancy for running school with and subject to compliance of the specific conditions as appended.

1.

2.

3.

4.

by sur Divisional ENGINEER

Sub Divisional Engineer Signature with Sea Provl. Sub Division PWD

Designation: Sub Division Engne

Name & Address of Department/ Office: pwn &c

<sup>\*</sup> Strike out whichever is not applicable. In case of block is more than six separate sheets for